


Belt-Driven Spindle – SBAX


<http://www.uskoreahotlink.com/products/manufacturing/high-frequency-spindles/>



A x B	Dimension									Speed
	K	I	e ₁	e ₂	b	M	I	SW	S	Max
	mm									Min ⁻¹
SBAX 60x110										
200	22	34	2.5	10	8	M12x1	10	19	8	20000
250										
315										
400										
500										18000
SBAX 70x200										
250	28	42	2.5	13	9	M15x1	11	24	10	18000
315										
400										
500										15000

Belt-Driven Spindle – SBAX


<http://www.uskoreahotlink.com/products/manufacturing/high-frequency-spindles/>



A x B	Dimension									Speed
	K	I	e ₁	e ₂	b	M	I	SW	S	Max
	mm									Min ⁻¹
SBAX 80x250	33	48	3.2	16	10	M20x1	12	27	12	15000
315										
400										
500										
630	43	63	3.2	16	10	M25x1	14	36	14	12500
SBAX 100x315										
400										
500										
630	800									10000
800										

Belt-Driven Spindle – SBAX


<http://www.uskoreahotlink.com/products/manufacturing/high-frequency-spindles/>



A x B	Dimension									Speed
	K	I	e ₁	e ₂	b	M	I	SW	S	Max
	mm									Min ⁻¹
SBAX 120x400										
500	53	70	4	18	12	M36x1.5	18	46	16	9000
630										
800										8000
SBAX 140x400										
500	58	63	5	20		M36x1.5	20	50	18	7500
630										

Belt-Driven Spindle – SBAX

<http://www.uskoreahotlink.com/products/manufacturing/high-frequency-spindles/>



A x B	Dimension									Speed
	K	I	e ₁	e ₂	b	M	I	SW	S	Max
	mm									Min ⁻¹
SBAX 160x400										
500	68	80	4	23		M40x1.5	20	60	20	7000
630										6000
SBAX 200x500										
630	90	100	6	6		M55x1.5	25	30	10	5000